

Opinion of the car Peugeot 406 Licence plate 715 AYM

1. Clutch operation failed during normal drive. After removing gearbox, it is obvious that clutch is already replaced lately. Clutch disk center part is teared apart from disk. No abuse is noticeable. Examination of gearbox oil showed that there is some wear inside gearbox, because large metal abrasives are in gearbox oil. Conclusion is that clutch disk is broken because of the gearbox failure. Gearbox need replacing or examination before installing new clutch.
2. Car has been in big accident. Left front corner frame is damaged, and replaced with aftermarket parts. Noticable is that framework is not done by professionals. It is cut from wrong place and welded together very badly.
3. The front panel of the car is heavyli damaged, because of wrong towing operation. For proper reappear front panel has to be changed, also front light mountings are cracked, radiator mountings cracked etc.